The Boeing Company
P.O. Box 516
St. Louis, MO 63166-0516
(314) 232-0232 TELEX 44-857

464C-4926-JWH 3 May 2000 REC'D

MAY 09 2000

RESP

Mr. Edwin Buckner U.S. Environmental Protection Agency Region VII ARTD/RESP 901 North 5th Street Kansas City, Kansas 66101-2907

RE:

April 25, 2000 hazardous waste compliance inspection of the McDonnell Douglas Corporation-Tract I facility pursuant to 40 CFR 265 Subparts AA, BB,

and CC.

Dear Mr. Buckner;

This letter is to inform you of corrective action taken following the compliance inspection conducted by Mr. David Whiting of Region VII. Based on OVA meter readings, emission levels for one 2 cubic yard container of hazardous solid waste exceeded the subpart CC regulatory limit.

This container was taken out of service on the morning of April 26, 2000. The container lids will be repaired to prevent detectable emissions from escaping. A repair record has also been implemented to track and document the repairs made to the solid hazardous waste containers.

A container inspection plan has been developed to ensure that containers used for the collection and storage of hazardous solid waste are visually inspected and tested for emissions on an annual basis. The plan also specifies that containers will be pulled out of service within 24 hours when a defect or excess emission is detected.

Please contact me should you need additional information.

Sincerely,

Joseph W. Haake. Group Manager

Environmental and Hazardous Materials Services

Dept. 464C, Bldg. 220, Mailcode S221-1400

(314) 232-6941

CC: David Whiting

RCRA RECORDS CENTER